

## 附件二

### 擬立面美化改善建築物現況相片

 A photograph showing the east facade of a two-story building. The building has a light-colored exterior with several windows. In the foreground, there are some potted plants with red flowers.	 A photograph showing the west facade of the building. The building has a light-colored exterior with a prominent dark staircase on the right side. A white car is parked in front of the building.
<p>建物現況東向立面相片</p>	<p>建物現況西向立面相片</p>
 A photograph showing the north facade of the building. The building has a light-colored exterior with several windows. A white car is parked in front of the building.	 A close-up photograph of the concrete staircase leading up to the building. The stairs are weathered and have a reddish-brown handrail on the left side.
<p>建物現況北面相片</p>	<p>建況建物樓梯相片</p>

### 附件三

現況環境相片



建物現況環境相片